

## Technical Data – HW-WS Hot-Wedge Welding Machine

<b>Parameter</b>	<b>Specification</b>
Welding speed	Up to 30 m/min
Temperature	Up to 500 °C
Voltage	1-phase 230 V, 50/60 Hz + earth, 16 A
Compressed air requirement	Minimum 7 bar
Air consumption	10 l/hour
Pressure range	15–70 kg